## Pedestrian Accessibility Plan

# Keeping pedestrians safe on Lisbon's streets

Tiago Cunha Aleixo, architect







# What is our mission?

## Define city strategies:


- more accessible
- more safety
- prevent new barriers in the public space

Why Pedestrian Accessibility?









### Cobblestone walkways:

- 1. Slippery,
- 2. Irregular joints,
- 3. Uneven surfaces, etc.

### Cobblestone walkways

They cause falls with sometimes serious injuries for pedestrians.



### **East station**

Public Space Actors

- 1. Lisbon train station, direction to :
  - A. North of Portugal
  - B. Lisbon city center
  - C. South of Portugal
- 2. Taxies (18 parking spaces)



#### **Crosswalk specification**





#### Ánalise Espacial



6








2010

Resultados dos Gráficos

N° de Vítimas por Atropelamentos 2010-2018 (Feridos a 3...



### Traffic count with the Miovision Scout


### **Methodology:**

Duration: 1 hour

• Time: 12:30 to 13:30

Day: Friday





# Pedestrian Count at East Station


Miovision Report

Total: 1657

Northbound: 642 (to East Station)

Southbound: 1015 (to shopping center)





# Vehicle Count at East Station

Miovision Report

Total: 1326

Northbound: 605

• Southbound: 723



# Conclusion of the count


Total vehicles: 1328

Total pedestrians: 1657

#### **Problem:**

- Pedestrians have 30 seconds to cross this 32,5m crosswalk.
- In 8 years there were 35 minor injuries, 3 serious of which 2 are in wheelchair now

Is it possible to improve the crossing for a better balance in the use of public spaces.





Tiago Cunha Aleixo

tiago.aleixo@cm-lisboa.pt



Roman Rohrberg

rrohrberg@miovision.com